

Attachment A – Description of Important Enhancements in WinRiver 10.06

- Fixed problem with receiving/decoding GPS data.
- Fixed problem when switching from Playback to Acquire Mode after installation.
- Changed wording for the User Options - Expert Tab - Data Recording description.
- Fixed problem with generating unnecessary message when attempting to load sequential transect after transect x99 (where x = 1... 9).
- Fixed problem with rounding of negative discharge in Q Measurement Wizard.
- Changed calculation of % Diff in Q Measurement Wizard (average discharge rounded to 3 significant digits).
- Fixed problem with Q Measurement Wizard that saved unlocked files as locked.
- Fixed problem with Configuration Wizard and Mode 11.
- Added resolution for latitude and longitude display.
- Fixed some views that displayed data referenced to "Bottom Track" even though "None" was selected.
- Changed order of "Set ADCP clock", "Set PC clock" items on the menu.
- Changed Discharge Profile plot not to display "Power Fit" line if "No Slip" method is selected.
- Fixed problem with vertical scaling of all plots when manually entering WK command in Acquire mode.
- Added upper limitation on WV calculated in Configuration Wizard (480 cm/s for Broadband and 700 cm/s for Workhorse).
- Changed Reference selection description on menu from "None" to "None (Boat Speed = 0)".
- Changed velocity reference description in Summary File and Discharge History Tabular from "ADCP" to "BTM".
- Enabled GGA quality code 9.