

## 6.7.5 REPORTING

ASTM and USEPA guidelines for reporting turbidity measurements are tabled below.

- ▶ **Record only NTU** (not FTU) values in the data base.
- ▶ Remember to multiply sample readings by the appropriate dilution factor to obtain a final turbidity value.

Table 6.7-4. Guidelines for reporting nephelometric turbidity measurements (from USEPA, 1990)

NTU	Record to nearest
0-1	0.05
1-10	0.1
10-40	1
40-100	5
100-400	10
400-1,000	50
>1,000	100