



Figure 3. Depth of inundation of the 50-year flood and location of cross sections on Río Choloma at Choloma, Honduras.