

Figure 5. Depth of inundation of the 50-year flood and location of cross sections on Río Tocoa at Tocoa, Honduras.